	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
Н	BRS	L2	197	(RADIANCE and (emissivity or emissivities) AND SURFACE)	USPAT; EPO	2001/01/12 12:12		
2	BRS	L3	151	2 and wavelength	USPAT; EPO	2001/01/12 12:13		
ω	BRS	L4	18	3 and (polarization or polarized)	USPAT; EPO	2001/01/12 12:14		
4	BRS	L5	18	4 and (planck or temperature)	USPAT; EPO	2001/01/12 12:16		
G	BRS	L6	7	4 AND PLANCK	USPAT; EPO	2001/01/12 12:16		
0	BRS	L7	2	5 and ((take adj off) or (take-off))	USPAT; EPO	2001/01/12 12:20		
7	BRS	L1	ω	surface and (radiance adj ratio)	USPAT; EPO	2001/01/12 12:19		
ω	BRS	L8	22500	(TAKE-OFF OR (TAKE ADJ OFF))	USPAT; EPO	2001/01/12 12:20		
9	BRS	L9	0	8 and polarizations and radiances	USPAT; EPO	2001/01/12 12:22		
10	BRS	L10	ω	8 and 3	USPAT; EPO	2001/01/12 12:22		

			:	3	,	- 1	) 	1
	туре	Ŀ #	HITS	Search Text	DBS	Time Scamp	Comments	Stamp   Comments   Error Delinition
Ъ	BRS	L1	1825	temperature and planck	USPAT; 2001/ EPO 12:42	2001/01/12 12:42		01/12
2	BRS	L2	729	l and (emission or emissivity or emissivities) EPO	USPAT; 2001/ EPO 12:43	2001/01/12 12:43		
ω	BRS	L3	588	2 and wavelength	USPAT; 2001/ EPO 12:43	2001/01/12 12:43		
4	BRS	L4	84	3 and (radiance or radiances)	USPAT; 2001/ EPO 12:44	01/12		
U	BRS	L5	7	4 and (polarization or polarized) EPO	USPAT; 2001/ EPO 12:45	01/12		

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
ш	BRS	L1	8844	((radiation adj detector) or (radiation adj detecting))	USPAT; EPO	2001/01/12 14:29		
2	BRS	L2	615	<pre>l and (polarizer or polarization or polarized)</pre>	USPAT; EPO	2001/01/12 14:30		
ω	BRS	L3	397	2 and wavelength	USPAT; EPO	2001/01/12 14:30		
4	BRS	L4	252	3 and (processor or processing or computer)	USPAT; EPO	2001/01/12 14:31		
5	BRS	L5	4	4 and radiance	USPAT; EPO	2001/01/12 14:32		
Q	BRS	L6	22	4 and (emissivity or emissivities)	USPAT; EPO	2001/01/12 14:36		
7	BRS	L7	2	6 and (radiance or radiances)	USPAT; EPO	2001/01/12 14:37		
ω	BRS	L8	22	6 and temperature	USPAT; EPO	2001/01/12 14:37		